# Prompt Gamma Analysis of RFETS and LLNL Items

Joshua Narlesky

Los Alamos National Laboratory NMT-11

October 24, 2002

# Prompt Gamma Studies

- Acknowledgement
  - Lynn Foster
  - Ric Mason
  - Larry Peppers
  - Paul Oppedal

# **Topics**

- Introduction
- Analysis Methods
- Prompt Gamma Results
- Analysis of Furnace 5 Failure
- Conclusion

#### Introduction

- In the past, working with radioactive containers was costly, time consuming and put people a risk of radiation uptake due to destructive analysis.
- Prompt Gamma offers a method of non-destructive analysis through selfinterrogation by alpha particles.
- This method is fast, safe, and inexpensive since the analysis can be done on sealed containers.



#### **Current Focus**

Identify cans containing high concentrations of impurities that are potentially corrosive or could lead to gas generation inside the 3013 containers leaving the Plutonium Stabilization and Packaging System.

Elements of interest: Al, Be, Cl, F, K, Mg, Na, Si

# **Analysis Methods**

#### Maestro Multi-channel Analyzer


- Calibrates channel data, locates and identifies peaks
- User defines a region of interest (ROI), and the peak area is determined for the peak in that region
- Cannot analyze broad, high-energy peaks
- Insufficient output generation


#### Prompt Gamma Analysis Software

- Interactive display designed using Matlab®
- Reads, plots, and calibrates channel data
- Locates peaks using the Generalized Second Derivative Method and determines the net counts
- Can analyze broad, high energy peaks
- Identifies peaks using library of alpha-induced reactions
- Lists all possible interferences
- Creates tables and graphs for MIS database

# **Analysis Methods**

#### **Peak Search Routine**






# **Analysis Methods**


 Most elements are positively identified in the sample by their corresponding primary peak.


Element	Primary Peaks (keV)	Secondary Peaks (keV)								
Al	2236	1263	3498	2476						
Ве	4439	3928	3417							
Cl	2168	1146								
F	1275	891	1236	2081						
K	1524									
Mg	1273	1014	2028	2839						
Na	1808	1130	2132	2938						
Si	2235	1266	1213	1779						

 Elements such as F, Mg, Al, and Si have interferences and require the primary and one or more secondary peaks for positive identification.





#### **Item Summary**






#### Raw Data Reports





#### **Prompt Gamma Results Summary**

Filename	Content									Comments			
	Αl	Ве	CI	Cr	Cu	F	Fe	Mg	K	Na	Si	Ta	
R400068.Chn						F		Mg					
R600093.Chn													no positive detection
R600094.Chn								Mg					
R600107.Chn						F		Mg					
R600110.Chn					Cu	F		Mg					
R6001116.Chn						F		Mg					
R600114.Chn													no positive detection
R600120.Chn													no positive detection
R600129.Chn		Ве			Cu			Mg		Na			
R600136.Chn													no positive detection
R600137.Chn													no positive detection
R600139.Chn								Mg					
R600140.Chn								Mg					
R601929.Chn						F		Mg					
R602005.Chn	Αl	Ве			Cu			Mg		Na	Si		Very large Be-peaks, missing Pu pks > 500 keV
R602167.Chn								Mg					
R602729.Chn		Ве			Cu			Mg					Very large Be-peaks, missing Pu pks > 500 keV
R602787.Chn	Αl		C					Mg			Si		



- Analyzed and unanalyzed data will also be put onto the ISP database.
- They will be passed on to the rest of the sites.
- Will be helpful to future surveillance and research projects.

#### Furnace 5 Failure







- Furnace sustained severe damage to support stand and right wall behind element.
- Exterior of furnace shows discoloration above door frame due to escaping gases.

#### Furnace 5 Failure

- The damage was discovered shortly the material for can R601284 was calcined.
- It was initially theorized that corrosive gases from this batch, released during calcination, were a direct cause of the damage to the furnace stand.
- Prompt Gamma showed only small amounts of Na and Mg in R601284.

#### Furnace 5 Failure

- RFETS then made a request for analysis of items that went into the furnace for 2 months prior to furnace failure.
- We pulled from the DB the last 30 items that fed into furnace 5 prior to failure.
- We researched feed combinations and IDC's looking for anything obvious.
- Used software to analyze individual items looking for any type of corrosive materials that prompt gamma could see.

#### Furnace 5 Results

- Most spectra contained small Mg peaks at 1274 keV and 1014 keV.
- Na, F, and Be were also detected in a few cans.
- Found no relationship between IDC and impurities found in sample.
- Cl not detected in any cans.

IDC	Description								
057	Pu oxide awaiting specification analysis. Includes								
	metal turnings, floor sweepings, fines, etc.								
060	High purity Pu oxide								
061	Pu oxide with high impurites								
U61	Pu / Enriched U oxide < 10,000 ppm Enriched U								
Y61	Pu / Enriched U oxide > 10,000 ppm Enriched U								

- 1150()			Positive
Feed IDC(s)	Item	LOI	Detection
057	R600333	0.073	Mg
	R600422	0.100	Mg
	R600819	0.095	Mg
	R601010	0.116	Mg
057/061	R600517	0.020	F, Mg
060	R600317	0.048	Mg
	R600350	0.038	Mg
	R600442	0.024	Mg
	R600802	0.108	F, Mg
	R600812	0.070	Mg
	R600914	0.028	
	R600927	0.130	Mg
	R600967	0.076	Mg
	R601063	0.090	Mg
	R601106	0.106	Mg
	R601146	0.080	Mg, Na
060/061	R600340	0.210	F, Mg
	R601046	0.000	Mg
	R601142	0.075	Mg
	R601208	0.090	F, Mg
060/U61/Y61	R600385	0.106	Mg, Be
061	R600357	0.032	Mg, Be
	R600785	0.118	F, Mg
	R601011	0.105	Mg
	R601284	0.230	Mg, Na
U61	R600263	0.074	
	R600477	0.114	Mg
U61/Y61	R601082	0.089	Mg, Na
Y61	R600931	0.112	Mg

#### Furnace 5 Results

- The prompt gamma results suggest several possible causes for the failure.
  - 1. Corrosive material evaporated during calcination and is no longer detectable with prompt gamma.
  - 2. Corrosive material is not detectable with prompt gamma.
  - 3. Damage occurred because of other causes such as the sensitization of 304 stainless steel that occurs due to repeated heating above 425° C.
  - 4. Supported RFETS working notion that CI, F are not the problem with these particular items.

# Limitations of Prompt Gamma

- Prompt Gamma Analysis yields only qualitative results for RFETS data.
- More research is required to obtain quantitative results due to the following limitations:
  - Lack of Chemical Data
  - Non-Homogeneous System
    - Limited Pu Contact
    - Limited Range of Alpha Particles
    - Varying Particle Size
  - Interference in Spectrum Data
  - Varying Conditions Measurement Time, Material Composition, Distance, and Shielding
  - Lack of Replication (1X or Reruns)

#### **Future Work**

- Continued Analysis of RFETS, LANL and any other sites Items.
- Continued refinement of analysis software to determine content of storage containers.
- Develop a model for the production and detection of gamma rays in pure materials.
- Design standards: Pu oxide mixtures with known particle size and chemical content.
- Determine the relationship between the standard mixtures and pure compounds.

# **Prompt Gamma**

Any questions?